

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 1Camp/121/24-25-

Dated: 16-03-2024

It is certified that the existing building Central Public School (name of the building or premises) at Utraut Chakiyā, Chandauli U.P.

(address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground II <sup>+</sup> Floors	-	-	-	-	-

The building is owned/occupied by CENTRAL PUBLIC SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD Chandauli (Name of Department/ Govt.) on 16/03/2024 (date of inspection) in the presence of Dr. Vinay K. Verma (Manager) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 16/03/24 for a period of (0.5) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. N.A
2. N.A
3. N.A
4. N.A

Issued on 16/03/24 at PWD-AE/II Chandauli by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Encl as below

- I - Checklist
- II - Dept. Letter
- III - Building Plan

68 | Page

- IV - Building Photo with Manager
- V - CBSE Letter.

Signature with Seal: [Signature]

Name: राधेश्याम सिंह

Designation: सहायक अभियंता

Name & Address of Department/ Office: चन्दौली (उ.प्र.)

सहायक अभियन्ता

प्रान्तीय खण्ड, लो०नि०वि०

चन्दौली